



Contractor All Risks for High Value Homeowners

1pm – Alexandra Suite CILA Conference 2016





Speakers

Bill Wilson

Director UK Operations



Insurance Engineering Services & Chairman of the CILA HNW & Specie SIG

Timothy Carpenter

London Manager for HNW



Cunningham Lindsey

Matt Deaville

Partner

Kennedys

Legal advice in black and white

Kennedys Law LLP



Market positioning









Case Study 1

Front view of risk address showing neighbouring property







Risk Address





- Parties Involved
 - Know who your dealing with
 - Interior Designer, Chief Executive & Retired Lawyer
- Contract Works:
 - Basement Extension and complete refurbishment





Contract Works

Basement Extension-Planning granted from Royal Borough of Kensington and Chelsea









Complete refurbishment works at risk address at first floor level at risk address

Rear Excavation works







Policy Cover – All Risks

- Existing Structure £1,000,000
- Contract Works £990,000
- Legal Liability as property owner Non Negligent Damage cover extension





Party Wall Awards

- What is an Award?
- Impact of an Award
- Copy of condition survey
- One or two surveyors?





Claim

- Damage to both neighbouring properties along the Party Wall
- Party Wall Surveyors fees for both neighbouring properties





Claim



Cracks under the stairs near Party Wall



Claim



Further Damage in neighbouring property No 15



Claim



Damage to neighbouring property along the Party Wall



Investigations

- Establishing all interested Parties
- Engaging all parties for the site meeting if possible.
- Engage both Party Wall Surveyors and obtain related documents
- Obtain required documentation of works being undertaken
 - JCT Contract
 - Method Statements



Issues / Remarks

- Planning Royal Borough of Kensington and Chelsea restrictions
- Absence of a Surveyor/project manager
- Absence of JCT contract
- Numerous subcontractors and building professionals i.e. surveyors, engineers, architects etc.
- Managing expectations/ tension between neighbours



Issues / Remarks:

- Tension between Party Wall surveyors
- Historic crack versus new
- Need to adopt a HNW style of handling
- Method of Settlement
- Claims can be long tail as no party can reach agreement until the final condition survey. In the meanwhile, evidence gathering and hand holding.
- Sometimes no claim at all or so minor that an agreement is reached that the Insured's contractor simply carries out the work at no extra cost.



Settlement & Outcome

- Settlement options
 - Cash or Reinstatement
 - Private agreement between parties
- Successful outcome for private homeowner and neighbours
- Insurers wanted to reinstate 3rd party however not agreeable under Party Wall Act



Case Study 2







Nature of Works

- Description of Works:
 - Garage conversion, refurbishment and basement extension







Underpinning and excavation works/rear extension

Ongoing works at risk address at second floor level





Ongoing works at first floor level- new beam installed.



Policy Cover

- Existing Structure
- Contract Works £517,000
- Liability as Property Owner No Non Negligent Damage Extension





Party Wall Award


- Party Wall Implications:
 - Was there an award? Not required at commencement
 - Changed design mid contract to include works to Party Wall
 - Absence of pre-condition survey





The Claim

- Damage to neighbours decorations on first floor in library along a Party Wall
- Surveyors fees incurred by the neighbour



Damage at the neighbouring property







Investigation

- Request for correct for relevant documentation
- First site meeting to Third Party Property and risk address with the Insured and neighbour
- Second site meeting with broker access to neighbours house





Liability Issues

- Claim initially repudiated as no Non-Negligent damage cover
- No Party Wall Award Insurers position prejudiced
- Established that after work commenced the contractor decided to carry out works along the Party Wall which were not originally planned. No initial requirement.
- No pre-condition survey



Liability Issues

- Broker with insured looked to pursue a claim against the contractor who excavated the basement.
- Basement Contractor and their Insurers/
 Adjusters looking to hold the main contractor
 liable as they suggest the damage was
 caused after they did the basement but
 caused by vibrations during the initial strip out
 works.



Liability Issues

- Adjusters for the basement company suggested a claim should be made by the Third Party for Nuisance
- Delay by the Insured and Third Party in submitting a claim - Insurers position prejudiced
- Other causes differential movement with coach house passageway
- Historic Movement



Adjustment

- Request for the neighbours to obtain an estimate for the damage
- Claim repudiated no cover for non negligent damage cover
- Exclusion no cover for legal liability in the absence of proven negligence by you or your contractor unless Insurers have included the Non Negligent Damage Extension
- Claim within the policy excess
- Suggested that the neighbour would have to prove negligence against them



Remedies/Recovery Targets


- Main Contractor
- Sub-Contractor
- Surveyor
- Architect
- Insurance Broker





Remedies/Recovery Targets

- Cause of Action:
 - Breach of Contract
 - Negligence
 - Nuisance
 - Trespass





Remedies/Recovery Targets

- Recovery:
 - Cost of repair/rectification
 - Cost of alternative accommodation
 - Out of pocket expenses
 - (Sometimes) Damages for loss of amenity /injury to feelings





Closing Statement

- Product development
- Market Study Direct policies
- Insurance Act







